





## **State Water Resources Control Board**

June 12, 2018

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7017 2680 0000 6195 8947

Mr. Mark Grushayev
Wastewater Treatment Manager
Sewerage Agency of Southern Marin
450 Sycamore Avenue
Mill Valley, California 94941
mgrushayev@cityofmillvalley.org

SUBJECT:

NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEM LOCATED AT SEWERAGE AGENCY OF SOUTHERN MARIN, 450 SYCAMORE

**AVENUE, MILL VALLEY** 

Dear Mr. Grushayev:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the UST at your facility on May 25, 2018, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and California Code of Regulations (CCR), title 23, chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Maintain Monitoring or Testing Records – There were no cathodic protection testing records onsite at the time of inspection.	Diesel	May 25, 2018	Ongoing	H&SC 25293; 23 CCR 2712(b)
2	Failure to Maintain Tank Information – In CERS, the tank monitoring section denotes the single-walled tank has a dry secondary and the recordkeeping section denotes the equipment maintenance and calibration records are not being kept.	Diesel	May 25, 2018	Ongoing	23 CCR 2711(a)

Office of Enforcement | 801 K Street, Suite 2300 | Sacramento, CA 95814 | 916.341.5272

FELICIA MARCUS, CHAIR | EILEEN SOBECK, EXECUTIVE DIRECTOR

No.	Violation	Tank	Start Date	Stop Date	Regulation
3	Failure to Maintain Plot Plan/Site Map – An approved plot plan/site map indicating the location of the product piping, tanks, and auxiliary equipment with respect to buildings or other landmarks, such as the street, was not available in CERS or onsite at the time of the inspection.	Diesel	May 25, 2018	Ongoing	23 CCR 2711(a)(8)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and Marin County Department of Public Works, Waste Management Division, within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

## **State Water Board**

Mr. Will Speth
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
801 K Street, Suite 2300
Sacramento, California 95814
will.speth@waterboards.ca.gov

## **Local CUPA**

Ms. Julia Barnes, Supervisor
Waste Management Division
Marin County Department of Public Works
1600 Los Gamos Drive, Suite 210
San Rafael, California 94903
jbarnes@marincounty.org

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,

Amantha Henkel

Senior Environmental Scientist

**UST Enforcement Unit** 

Office of Enforcement

CC:

See next page.

cc: (via email only

Ms. Julia Barnes Supervising Hazardous Material Specialist Marin County Department of Public Works jbarnes@marincounty.org

Ms. Christie Coleman
Hazardous Material Specialist
Marin County Department of Public Works
ccoleman@marincounty.org

Mark Wilson
Maintenance Supervisor
Sewerage Agency of Southern Marin
mwilson@cityofmillvalley.org

Mr. Chris Monti Chief Treatment Plant Operator Sewerage Agency of Southern Marin cmonti@cityofmillvalley.org